



► Feature:

1. Four-in-one monitoring of temperature and humidity, PM2.5, and formaldehyde sensors
2. Working environment: -10~50 degrees, 15~90%RH
3. Measurement range: air temperature -40~80°C; air humidity 0~100% RH; PM2.5 0~999ug/m3; formaldehyde 0~2mg/m3
4. A separate power supply is required